PF REPORTER

1958 Subject Reference Index

This index has been prepared to provide you with a ready reference to all PF REPORTER articles published during 1958.

Items dealing with different phases of electronic theory and servicing are listed under major subject headings in boldface type. Individual subjects are listed alphabetically under each major heading, and the article title along with the month it appeared is shown in italics.

For subjects treated during any year from 1953 through 1956, consult the Subject Reference Index in the December issue for that year. The 1957 Index was published separately; free copies are available on request. Many back issues of PF REPORTER are available at 50c per copy.

ANTENNAS

Conical
Shop Talk ..... *Apr.*
Demonstration setup
Quicker Servicing ..... *Dec.*
Dipole theory
Shop Talk ..... *Feb.*
Folded dipole
Shop Talk ..... *Mar.*
High-gain types
—Channel Master "Rainbow"
Shop Talk ..... *May*
—Channel Master "Traveling Wave"
Shop Talk ..... *May*
—Clear Beam "Tri-King"
Shop Talk ..... *May*
—Finney Model TCR-1
Shop Talk ..... *July*
—JFD "Satellite-Helix"
Shop Talk ..... *July*
—JFD "Wonder-Helix"
Shop Talk ..... *May*
—TACO "Trapper"
Shop Talk ..... *May*
—Trio "Zephyr"; "Color Royal"
Shop Talk ..... *July*
—Winegard "Color 'Ceptor"
Shop Talk ..... *July*
Indoor types
What Do You Know About Indoor Antennas? ..... *Mar.*
Master antenna system for shop
Quicker Servicing ..... *July*
Multiple outlets for one set
Quicker Servicing ..... *Nov.*
Reflectors and directors
Shop Talk ..... *Mar.*
Stacking
Shop Talk ..... *Apr.*
Tower erection
Setting Up a Tower ..... *Sept.*
Yagi design
Shop Talk ..... *Apr.*

AUDIO & HI-FI

AM-FM tuner
—Hoffman Chassis 1110
Audio Facts ..... *Apr.*
—Madison Fielding stereo, Series 330
Servicing New Designs ..... *Nov.*
Amplifier
—General Electric Model PA-20
Audio Facts ..... *Apr.*
—EICO Model HF-21
Audio Facts ..... *June*
Distortion in hi-fi sound
Audio Facts ..... *Dec.*
Equalization networks
Audio Facts ..... *Feb.*
FM booster, Jerrold Model DSA-FM
Audio Facts ..... *Apr.*
FM tuner, J. W. Miller Model 560
Audio Facts ..... *Apr.*
Hi-fi system servicing
—basic discussion
Audio Facts ..... *Oct.*
—localizing troubles
Audio Facts ..... *Dec.*
Magnetic tape preamplifier, Electro-Voice 6010
Audio Facts ..... *Feb.*
Noise in hi-fi system
Audio Facts ..... *Dec.*
"Package" hi-fi unit, Columbia Model 583
Audio Facts ..... *Feb.*
Phono cartridge servicing
Phono Cartridge Replacement ..... *June*
Record changers
—Admiral Model RC-607
Hints on Record Changer Servicing ..... *May*
—Collaro "Conquest"
Hints on Record Changer Servicing ..... *May*
—Garrard Model RO 121/4
Hints on Record Changer Servicing ..... *Sept.*
—Monarch Model UA-8
Hints on Record Changer Servicing ..... *Sept.*
—V-M Model 1200A
Hints on Record Changer Servicing ..... *May*
—Webcor Model 151
Hints on Record Changer Servicing ..... *Sept.*
—Zenith Model S-14086
Hints on Record Changer Servicing ..... *Sept.*
Signal-generator test for amplifiers
Audio Facts ..... *June*
Speakers
—basic construction
Audio Facts ..... *Apr.*
—Cone types
Audio Facts ..... *June*
—Horns and drivers
Audio Facts ..... *Aug.*
Stereo
—cartridge specs
Converting to Stereo Disc Reproduction ..... *July*
—Components required for system
Converting to Stereo Disc Reproduction ..... *July*
—preamp, Pilot SM244
Audio Facts ..... *June*
—preamp design
Audio Facts ..... *Aug.*
—Westrex 45/45 disc recording system
Converting to Stereo Disc Reproduction ..... *July*
Stylus balance scale
Audio Facts ..... *June*
Stylus wear
Quicker Servicing ..... *May*
Tape recorder reel squeak
Troubleshooter ..... *June*
Turntable re-flocking
Quicker Servicing ..... *July*

BUSINESS

Customer complaints
—common causes
Let's Talk Business ..... *June*
Estimating service charges in advance
Give Estimates—Stop Aggravation ..... *Sept.*
Guaranteeing service work
Solving the Guarantee Headache ..... *Apr.*
Increasing your business
Quicker Servicing ..... *Jan.*
Premiums for advertising use
Dollar & Sense Servicing ..... *Apr.*
Renting shop space
Dollar & Sense Servicing ..... *May*
Renting used TV's
Dollar & Sense Servicing ..... *Jan.*
Sales sidelines
Walk-In Sales Items for the Service Shop ..... *June*
Time utilization
Quicker Servicing ..... *Nov.*
Wife helping in service business
Let's Talk Business ..... *Feb.*

CIRCUIT & CHASSIS DESIGN

AGC
—control in Packard-Bell Chassis V8-2
AGC Circuits for '58 ..... *June*
—switch in Motorola Chassis TS-292C
Troubleshooter ..... *Jan.*
—switch in RCA Chassis KCS47
Across the Bench ..... *Dec.*
—6BU8 circuits:
(in Admiral Chassis 16J1)
AGC Circuits for '58 ..... *Apr.*
(in DuMont Chassis RA-400)
AGC Circuits for '58 ..... *June*
(in Motorola Chassis TS-542)
AGC Circuits for '58 ..... *June*
(in Zenith Chassis 15A25 and 17A20)
AGC Circuits for '58 ..... *Apr.*
Automatic fine tuning in Westinghouse Chassis V-2372
Now—Automatic Fine Tuning ..... *Feb.*
Contrast control in AGC circuit, Philco Chassis 8L35
AGC Circuits for '58 ..... *June*
DC restorer in RCA Chassis KCS47
Across the Bench ..... *Dec.*
Fine tuning arrangement in RCA Chassis KCS121
Servicing New Designs ..... *Sept.*
Fringe compensator circuit in Emerson Chassis 120169B
Troubleshooter ..... *July*

General Electric "Designer" Series receivers
Servicing New Designs ..... *July*
IF strip with one stage, Olympic Chassis DY
Servicing New Designs ..... *May*
Line voltage adjustment, Magnavox 26 Series chassis
Servicing New Designs ..... *May*
Printed wiring
Servicing Printed Wiring Boards ..... *Oct.*
Remote control, Admiral "Son-r"
Servicing New Designs ..... *Mar.*
Sound detector in General Electric Chassis Q3
Servicing New Designs ..... *July*
Speaker systems in TV
Servicing New Designs ..... *Nov.*
Vertical retrace blanking
Vertical Retrace Line Elimination ..... *Aug.*

COLOR TV

"Burned-in" color bar pattern
Quicker Servicing ..... *Mar.*
Convergence affected by vertical sweep trouble
Quicker Servicing ..... *Dec.*
Color stripe test jack, Admiral Model 29Z1
Quicker Servicing ..... *Mar.*
Color sync servicing
Fine Points in Color Sync Servicing ..... *May*
Dot generator pattern stability
Troubleshooter ..... *Aug.*
Focus circuit change, RCA
Quicker Servicing ..... *Mar.*
Grey scale setup
Troubleshooter ..... *Feb.*
RCA Chassis CTC7 features
Servicing New Designs ..... *May*

COMPONENTS & PRODUCTS

Automobile battery polarity
Guide to Automobile Battery Polarities ..... *Mar.*
Contact cleaner "injector"
Quicker Servicing ..... *Mar.*
Electrolytic capacitors
Check Those Electrolytics ..... *Oct.*
Fusible resistors
—failures
Quicker Servicing ..... *Jan.*
—part numbers and values
Quicker Servicing ..... *Dec.*
Garage door openers
Installing Electronic Garage Door Openers ..... *July*
Hand tools
Selection and Use of Hand Tools ..... *Jan., Mar.*
Lamp with magnetic base
Quicker Servicing ..... *Feb.*
Multiple outlet strips
Quicker Servicing ..... *Apr.*
Newly introduced
Product Report ..... *All Issues*
Soldering iron tips for printed circuits
Quicker Servicing ..... *Aug.*
Wire and cable
Wire and Its Uses ..... *Feb.*
Yokes
Replacing Deflection Yokes ..... *May*

INDUSTRIAL ELECTRONICS

Binary counters
Servicing Industrial Electronics ... *May*
Binary-to-decade converter
Servicing Industrial Electronics ... *July*
Computer circuits
Servicing Industrial Electronics ... *May*
Conductivity sensing of liquids
Servicing Industrial Electronics ... *Feb.*
Decade counters
Servicing Industrial Electronics ... *Sept.*
Density measurement of liquids
Servicing Industrial Electronics .... *Jan.*
Digital readout lamps
Servicing Industrial Electronics .... *July*
Eccles-Jordan circuit
Servicing Industrial Electronics ..... *May, July*
Flaw detection
Servicing Industrial Electronics ... *Mar.*
Gas-glow counter tubes
Servicing Industrial Electronics ... *Sept.*
Hydrometer
Servicing Industrial Electronics .... *Jan.*
Liquid level sensers
Servicing Industrial Electronics .... *Jan.*
MBS tubes
Servicing Industrial Electronics ... *Sept.*
Oxidation-reduction potential
Servicing Industrial Electronics ... *Feb.*
pH sensers
Servicing Industrial Electronics ... *Feb.*
Photocells as control devices
Servicing Industrial Electronics ... *Apr.*
Timers
Servicing Industrial Electronics ... *Nov.*
Thickness measurement
Servicing Industrial Electronics ..... *Mar., Apr.*
Vibration sensers
Servicing Industrial Electronics ... *Mar.*
Viscosity measurement
Servicing Industrial Electronics .... *Jan.*

PICTURE TUBES

Glass replacement for metal
Replacing Metal CRT's with Glass ..... *May*
Low Eg2 types
Quicker Servicing ..... *Aug.*
Peculiar troubles caused by CRT
Quicker Servicing ..... *Apr.*
110°, 8" check tube
Quicker Servicing ..... *May*
110° CRT bases
Servicing New Designs ..... *May*
Letters to Editor ..... *Nov.*

PREVIEWS OF NEW SETS

Admiral Chassis 18A6 ..... *Sept.*
Airline Chassis V2365-5 ..... *Sept.*
Andrea Chassis VQ21-110 ..... *Nov.*
General Electric Chassis U3 ..... *Dec.*
Hoffman Chassis 341 ..... *Dec.*
Motorola Chassis PTS-546Y ..... *Oct.*
Olympic Chassis HB ..... *Oct.*
Packard-Bell Chassis 98D4 ..... *Oct.*
Philco Chassis 9H25U ..... *Dec.*
Philco Chassis 9L60 ..... *Sept.*
RCA Chassis KCS121E ..... *Sept.*
RCA Chassis KCS122BAB ..... *Nov.*
Setchell-Carlson Chassis C105 ..... *Dec.*
Silvertone Chassis 528.51400 ..... *Oct.*
Sylvania Chassis 1-542-3 ..... *Nov.*
Zenith Chassis 19B20UD ..... *Nov.*

RADIO

Antenna circuit burnout
Troubleshooter ..... *Nov.*
Automobile radio
—all-transistorized, Motorola Model GV-800
Servicing New Designs ..... *Sept.*
—FM, Lincoln Model 88BH
Servicing New Designs ..... *July*
—vibrator buzz
Troubleshooter ..... *May*
FM radio theory
FM Signal ..... *July*
German-made auto radio
Quicker Servicing ..... *June*
Transistorized portables
—disassembly
Pocket-Sized Portables ..... *July*
—troubleshooting hints
Advanced Troubleshooting Techniques for Transistor Radios ..... *Aug.*
Tube failure in portables
Quicker Servicing ..... *May*

SERVICING

AGC
—excessive, in RCA Chassis KCS92D
Troubleshooter ..... *Sept.*
—insufficient, in Sparton Chassis 22V214
Troubleshooter ..... *Aug.*
—repairs, in RCA Chassis KCS47
Across the Bench ..... *Dec.*
Air-conditioner troubleshooting
Servicing the Summer Air Conditioner ..... *Aug.*
Alignment
—FM sound circuits
Quicker Servicing ..... *May*
—IF in TV sets
Behind the IF Alignment Scene ..... *Apr.*
IF Alignment Made Easy ..... *Dec.*
—Test equipment checkout
Troubleshooter ..... *Dec.*
—Transistor portable radio
Advanced Troubleshooting Techniques for Transistor Radios ..... *Aug.*
—Tuner
Troubleshooter ..... *Oct.*
Antennas
—demonstration setup
Quicker Servicing ..... *Dec.*
—tower erection
Setting Up a Tower ..... *Sept.*
Appliances
Small Appliance Servicing ..... *Aug.*
Audio output tube as B+ voltage divider
Quicker Servicing ..... *Feb.*
Check Those Electrolytics ..... *Oct.*
B+ too low
Troubleshooter ..... *June, Oct.*
Bench construction idea
A While-U-Wait Repair Bench .. *July*
Boost voltage
Letters to Editor ..... *Nov.*
Bottom fringes of white on picture, in Silvertone Chassis 478.309
Troubleshooter ..... *Oct.*
Buzz in RCA Chassis KCS88
Troubleshooter ..... *Dec.*
"C" clip removal tool
Quicker Servicing ..... *Oct.*
Capacitor leakage checks
Quicker Servicing ..... *July*
CRT testing in home
Quicker Servicing ..... *Feb.*
Chassis cradle
Quicker Servicing ..... *Oct.*
Christmas-tree effect
Pulse-Width Horizontal AFC .... *July*
Troubleshooter ..... *Sept.*
Co-channel interference
Troubleshooter ..... *Sept.*
Contrast-control failures in RCA 17" portable
System for Starting on Dogs ..... *Feb.*
Damper shorted in Admiral Model 36X36
Across the Bench ..... *Aug.*
Demagnetization of tools
Quicker Servicing ..... *Aug.*
Electrolytic capacitors
—leakage checks
Troubleshooter ..... *Sept.*
—service pointers
Check Those Electrolytics ..... *Oct.*
Fusible resistors
—blowing in RCA Chassis KCS109
Troubleshooter ..... *July*
—Part numbers and values
Quicker Servicing ..... *Dec.*
Garage door openers
Installing Electronic Garage Door Openers ..... *July*
Grid blocking in IF, Emerson Model 1155
Troubleshooter ..... *Feb.*
High voltage fuse blowing

—in RCA Model 630-TS
Troubleshooter ..... *Jan.*
—in RCA Chassis KCS108
Troubleshooter ..... *July*
Horizontal AFC, pulse-width type
Pulse-Width Horizontal AFC .... *July*
Horizontal multivibrator
Troubleshooting the horizontal multivibrator ..... *Oct.*
Horizontal oscillator
—far off frequency
Troubleshooter ..... *Oct.*
—insulation breakdown in DuMont Chassis RA-400
Troubleshooter ..... *Oct.*
—load capacitor
Troubleshooter ..... *Dec.*
Horizontal output
—excessive current (Magnavox Model 108B)
Across the Bench ..... *June*
(Sparton Model 5298)
Troubleshooter ..... *Sept.*
—resistor troubles
Quicker Servicing ..... *Mar.*
Horizontal sweep
—drive signal defective, DuMont Chassis RA-340
Troubleshooter ..... *Aug*
—lack of width, RCA Chassis KCS68CB
Troubleshooter ..... *July*
—loss of
Troubleshooter ..... *June, Sept.*
—shrinkage, RCA Model 21T7375
Troubleshooter ..... *Apr.*
—troubles due to faulty electrolytic capacitors
Check Those Electrolytics ..... *Oct.*
Horizontal sync
—bending (basic analysis)
Suffering From the Bends ..... *Jan.*
(General Electric Model 17C103)
Troubleshooter ..... *June*
(Motorola Chassis TS-307)
Troubleshooter ..... *Oct.*
(Packard-Bell Model 2710)
Troubleshooter ..... *Aug.*
(Philco Model 52T2256)
Troubleshooter ..... *Apr.*
—jitter
(Packard-Bell Model 21VT1)
Troubleshooter ..... *Aug.*
(Silvertone Chassis 456.-150-22)
Troubleshooter ..... *Apr.*
—pulling
(Meteor Model 7146)
Troubleshooter ..... *Sept.*
(Raytheon Chassis 21T19)
Troubleshooter ..... *Apr.*
(Zenith Chassis 17Z230Q)
Troubleshooter ..... *July*
—shifting
Troubleshooting with George .... *Feb.*
—trouble isolation procedure
Quicker Servicing ..... *Nov.*
Hot-chassis servicing
Troubleshooter ..... *June*
Hum in picture, how to isolate
Suffering From the Bends ..... *Jan.*
A System for Starting on Dogs ... *Feb.*
Ion trap magnet
—adjustment
Troubleshooter ..... *June*
—replacement
Troubleshooter ..... *Jan.*
—testing
Letters to Editor ..... *Oct.*
Keyed AGC
Quicker Servicing ..... *Feb.*
Left side of picture darker than right side
A System for Starting on Dogs .. *Feb.*
Low-capacitance probe usage
Probing for Trouble ..... *Nov.*
Low-frequency distortion in video amplifiers
Troubleshooting by Waveform Analysis ..... *Dec.*
Miscellaneous shop hints
Tips for Techs. ..... *Sept. thru Dec.*
Mistakes in wiring
Do-It-Yourselfers Are Soldering Now ..... *Mar.*
Motorboating during warmup
Troubleshooting With George .... *Feb.*
Negative picture
—in Emerson Model 1114J
Troubleshooter ..... *Nov.*
—in General Electric Model 21C137
Quicker Servicing ..... *Jan.*
—in Motorola Chassis TS-292C
Troubleshooter ..... *Jan.*
Noise inverter triode
Troubleshooting With George ... *Feb.*
Noisy operation due to loose tube-socket pins
Quicker Servicing ..... *July*
Overseas use of American radios and TV's
Letters to Editor ..... *June*
Philco split-chassis TV set, general overhaul
Across the Bench ..... *Oct.*
Pie-crust effect
—in Admiral Chassis 19K1
Troubleshooter ..... *May*
—in Emerson Chassis 120144B
Troubleshooter ..... *June*
—in Hallicrafters Model 680
Troubleshooter ..... *June*
—in pulse-width circuits
Pulse-Width Horizontal AFC .... *July*
Police radio interference
Troubleshooter ..... *Aug.*
Power supplies
Check Those Electrolytics ..... *Oct.*
Printed wiring
—case histories of troubles
Servicing Printed Wiring Boards .. *Oct.*
—repair techniques
Helpful Hints for PC Servicing .. *Dec.*
—soldering iron ttips
Quicker Servicing ..... *Aug.*
RCA Chassis KCS47, overhauling
Across the Bench ..... *Dec.*
RF-IF trouble analysis
Signal Tracing in RF-IF Circuits ..... *Mar.*
Regeneration in IF strip
Regeneration ..... *Feb.*
Ringing
—in video amplifier
Troubleshooting by Waveform Analysis ..... *Dec.*
—in yoke
Replacing Deflection Yokes ..... *May*
Selenium diodes in horizontal AFC
Troubleshooter ..... *Sept.*
Service literature
Quicker Servicing ..... *Sept.*
Signal injection
—across bypass capacitors
Shop Talk ..... *Sept.*
—into RF-IF stages
Signal Tracing RF and IF Circuits ..... *Mar.*
Shop Talk ..... *Sept.*
Snivets
Troubleshooter ..... *June*
Soldering gun holster
Quicker Servicing ..... *Oct.*
Sound garbling in Motorola Chassis TS-533Y
Troubleshooter ..... *Sept.*
Squegging
Pulse-Width Horizontal AFC .... *July*
Troubleshooter ..... *Sept.*
Sweep circuit waveforms
Using a Scope to Troubleshoot Sweep Circuits ..... *Mar.*
Sync loss in Motorola Model 17T22
Troubleshooter ..... *July*
Sync separator
Troubleshooting Sync Separator Systems ..... *April*
Test lead storage
Quicker Servicing ..... *Oct.*
Transistorized portable radios
—disassembly
Pocket-Sized Portables ..... *July*
—troubleshooting hints
Advanced Troubleshooting Techniques for Transistor Radios ..... *Aug.*
Tubes in wrong sockets
Quicker Servicing ..... *Apr.*
Tuner
—alignment in Raytheon Model M1611
Troubleshooter ..... *Dec.*
—detent lubrication
Quicker Servicing ..... *Jan.*
—frequency response check
Notes on Test Equipment ..... *Mar.*
—oscillator adjustment
Troubleshooter ..... *Mar, Oct.*
—poor reception on one channel
Across the Bench ..... *June*
—replacement with different type
Troubleshooter ..... *Feb.*
—switch-type unit disassembly
Servicing Switch-Type Tuners .... *Nov.*
—typical voltages applied
Troubleshooter ..... *Nov.*
Vertical blanking bar as troubleshooting aid
Troubleshooting Sync Separator Systems ..... *Apr.*
Vertical retrace blanking
—installation
Vertical Retrace Line Elimination ..... *Aug.*
—shorted in RCA Chassis KCS102
Across the Bench ..... *June*
Vertical sweep
—foldover in Emerson Chassis 120133B
Troubleshooter ..... *Nov.*
—general service hints
Analyzing the Vertical Circuit .. *June*
—insufficient in General Electric Model 21C201
Troubleshooter ..... *Apr.*
—loss in General Electric Model 14C102
Troubleshooter ..... *Feb.*
—troubles due to faulty electrolytic capacitors
Check Those Electrolytics ..... *Oct.*
Vertical sync
—frequency drift in General Electric Model 21C113
Troubleshooter ..... *July*
—intermittent roll in Zenith Model R2671E
Troubleshooter ..... *May*
—jitter in Admiral Chassis 22P2
Troubleshooter ..... *Apr.*
—poor
(General Electric "K" Line)
Troubleshooter ..... *May*
(General Electric Model 21C238)
Troubleshooter ..... *May*
(Philco Model A-T1818)
Troubleshooter ..... *Mar.*
—rolling back and forth in Emerson Chassis 120169B
Troubleshooter ..... *July*
Waveforms (normal) at typical TV check points
Troubleshooting With the Scope .. *Jan.*
X-ray radiation
Letters to Editor ..... *July, Oct.*
Yoke
—removal: effect on high voltage
Troubleshooter ..... *Apr.*
—replacement
Replacing Deflection Yokes ..... *May*

TEST EQUIPMENT

Absorption analyzer, Kingston Model EA-1
Notes on Test Equipment ..... *Aug.*
AC VTVM, RCA Model WV-74A
Audio Facts ..... *June*
Alignment setup pre-check
Troubleshooter ..... *Dec.*
Capacitor analyzer
—Pyramid Model CRA-2
Notes on Test Equipment ..... *June*
—Sprague Model TO-5
Notes on Test Equipment ..... *Mar.*
CRT reactivator-tester, Vis-U-All Model 200
Notes on Test Equipment ..... *Dec.*
Color pattern generator (bar, dot, etc.)
—Hycon Model 616
Notes on Test Equipment ..... *Nov.*
—Simpson Model 430
Notes on Test Equipment ..... *June*
Winston Model 250
Notes on Test Equipment ..... *Jan.*
DC power supply
—ATR Model 610C-ELIF
Notes on Test Equipment ..... *Jan.*
—Electro Model PS-2
Notes on Test Equipment ..... *Sept.*
Demodulator probes
—Doss Model D200 "Video Master"
Notes on Test Equipment ..... *May*
—General information
Signal Tracing RF and IF Circuits ..... *Mar.*
Electronic switch, B & M Model ES-40
Notes on Test Equipment ..... *Nov.*
Field strength meter
—Blonder-Tongue Model FSM-1
Notes on Test Equipment ..... *May*
—Simpson Model 498-A
Notes on Test Equipment ..... *Dec.*
Flyback and yoke tester, EICO Model 944
Notes on Test Equipment ..... *Apr.*
Flying spot scanner
—Hickok "Video Scanner" Model 760
Notes on Test Equipment ..... *Mar.*
—B & K "Analyst" Model 1075
Notes on Test Equipment ..... *June*
Induced waveform analyzer, Winston Model 850
Notes on Test Equipment ..... *May*
LC checker, Aerovox Model 97
Notes on Test Equipment ..... *Sept.*
Line current tester, Sencore "Fuse Safe" Model FS-3
Quicker Servicing ..... *June*
Marker adder, RCA Model WR-70A
Notes on Test Equipment ..... *Oct.*
Oscilloscope
—basic instructions for use
How to Use a Scope ..... *Oct.*
—kit, Paco Model S-50
Notes on Test Equipment ..... *May*
—Signal tracing hints
Using the Scope for Signal Tracing ..... *Apr.*
—Simpson Model 466
Notes on Test Equipment ..... *Aug.*
—techniques for examining sweep waveforms
Using Scope to Troubleshoot Sweep Circuits ..... *Mar.*
—waveforms at common TV check points
Troubleshooting With the Scope .. *Jan.*
Probes
—capacitive-divider and low-capacitance
Probing for Trouble ..... *Nov.*
—Doss units
Notes on Test Equipment ..... *Sept.*
—proper use with scope
Using a Scope for Signal Tracing . *Apr.*
Signal-tracing probe, Kingston "Probe-Master"
Notes on Test Equipment ..... *Jan.*
Square-wave generator test for video amplifier
Troubleshooting by Waveform Analysis ..... *Dec.*
Sweep and marker generator
—EICO Model 368
Notes on Test Equipment ..... *Jan.*
—Hickok Model 615
Notes on Test Equipment ..... *June*
Transistor checker
—Sencore Model TRC-4
Notes on Test Equipment ..... *Apr.*
—Triplett Model 690
Notes on Test Equipment ..... *Aug.*
Tube tester
—B & K "Dyna-Quik" Model 650
Notes on Test Equipment ..... *Mar.*
—Hickok "Cardmatic"
Notes on Test Equipment ..... *Aug.*
—Vis-U-All Model V1001
Notes on Test Equipment ..... *Sept.*
Vibrator checker, EMC Model 906
Notes on Test Equipment ..... *Apr.*
Volt-ohmmeter
—Precision App. Model 120M
Notes on Test Equipment ..... *Apr.*
—Simpson Model 260, Series II
Notes on Test Equipment ..... *Mar.*
—Triplett Model 630-PL
Notes on Test Equipment ..... *Oct.*
—use on hot chassis
Troubleshooter ..... *June*
VTVM
—RCA Model WV-77C
Notes on Test Equipment ..... *Dec.*
—Simpson Model 311
Notes on Test Equipment ..... *Nov.*

THEORY

Air conditioning
Servicing the Summer Air Conditioner ..... *Aug.*
Antenna principles
Shop Talk ..... *Feb., Mar., Apr.*
Audio output tube as voltage divider in power supply
Quicker Servicing ..... *Feb.*
Binary numbers for computers
Servicing Industrial Electronics .. *May*
FM radio transmission
The FM Signal ..... *July*
Graph interpretation
Shop Talk ..... *Jan.*
Horizontal multivibrator
Troubleshooting the Horizontal Multivibrator ..... *Oct.*
Horizontal output and high voltage circuit resistances
Quicker Servicing ..... *Mar.*
Multiplex FM broadcasting
The FM Signal ..... *July*
Polar graphs
Shop Talk ..... *Jan.*
Pulse width horizontal circuit
Pulse-Width Horizontal AFC .... *July*
RC coupling
Troubleshooter ..... *Nov.*
Vertical blocking oscillator
Keeping Up With Vertical Sweep . *Jan.*
Vertical sweep circuits
Analyzing the Vertical Circuit ... *June*

TRANSISTORS & APPLICATIONS

Auto radio, all-transistor
Servicing New Designs ..... *Sept.*
Interchangeability of types
Servicing New Designs ..... *Nov.*
Portable radios
—disassembly
Pocket-Sized Portables ..... *July*
—troubleshooting hints
Advanced Troubleshooting Techniques for Transistor Radios ... *Aug.*
—with phonograph
Servicing New Designs ..... *Mar.*
Silicone grease for power transistors
Quicker Servicing ..... *Oct.*
Telling p-n-p from n-p-n
Dollar & Sense Servicing ..... *Mar.*
TV receiver by Texas Instruments, Inc.
Shop Talk ..... *Nov.*

TUBES

Audio types most often used
Audio Facts ..... *Oct.*
European types
Guide to European Tubes ..... *Sept.*
Letters to Editor ..... *Nov.*
Stock requirements
Stock Guide ..... *Jan., Apr., Oct.*
Substitution guide
Quicker Servicing ..... *June*
6BU8 as AGC amplifier
AGC Circuits for '58 ..... *Apr., June*

VIDEO SPEED SERVICING

Airline Model WG-4204A ..... *Nov.*
DuMont Chassis RA-402 ..... *Oct.*
Emerson Chassis 120341H ..... *Sept.*
General Electric Chassis M3 ..... *Sept.*
Motorola Chassis TS-542 ..... *Dec.*
Packard-Bell Chassis 88S4 ..... *Oct.*
RCA Chassis KCS108C ..... *Nov.*
Sylvania Chassis 1-537-1 ..... *Dec.*

RF REPORTER . . .

. . . THE magazine for professional electronic servicemen, because it contains *more* articles on *more* subjects than any other publication in its field.

You'll find members of our editorial staff ready and willing to help you with any technical problem, whether it be a "tough dog" TV set, proper use of test instruments, or even locating a supplier for specific units or components.

published by HOWARD W. SAMS & CO., INC., Indianapolis 6, Indiana